


AIR SPRING – Hendrickson 57122-2 , W01-358-9373 , 1403551 , 1T15MT-8 – COMPLETE 4R-395/BIV/PR110/RP

APPLICATION – DAF 55

REPLACES – air spring , luftfeder Hendrickson – 57122-2,
W01-358-9373 , 1403551 , 1T15MT-8

MANUFACTURER – Rołgum, Poznań, PL



Zastosowanie: Daf 55, Iveco

Zamienniki: W01-358-9373

Hendrickson 57122-2